




WO 2005/064281 PCT/EP2004/014867 4/41










7/41 START IN SI 52 applying first pulse ~ applying second pulse 40 piuning risions? applying third pulse for applying fourth pulse End or 57 Fig. 7


• . .





WO 2005/064281


















Fig.13








Fig. 14





Fg.15





Fb.16
















Fg. 20














Fig. 23












Fig. 28








Signal (mV/Nm) and Signal Efficiency (µV/(Nm*A)) vs Current at 15mm Shaft

















Fig 45




Fig. 46








Fig. FI








WO 2005/064281 PCT/EP2004/014867


















Interrupted Transmission Input Shaft



Stand-Alone Torque Sensor







Fig. 57















Fig.62










































Fig.84






Fig. 86





Fig.87



F19.88

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

□ BLACK BORDERS
□ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
□ FADED TEXT OR DRAWING
□ BEURRED OR ILLEGIBLE TEXT OR DRAWING
□ SKEWED/SLANTED IMAGES
□ COLOR OR BLACK AND WHITE PHOTOGRAPHS
□ GRAY SCALE DOCUMENTS
□ LINES OR MARKS ON ORIGINAL DOCUMENT
□ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.